

Personal Protective Equipment; PPE

The wearing of PPE is in addition to the standard safety equipment associated with this shop facility.

Safety glasses must be worn at all times. When in doubt, ask the instructor. Do not assume

Welding

- welding jacket
- welding gloves
- welding helmet
- coveralls/apron
- face/filter mask (optional)

Grinding (hand grinder)

- gloves (work style or welding style, not latex, rubber, etc.)
- face shield
- hearing protection (optional)
- face/filter mask

Pedestal Grinder

- coverall/apron